Heat Exchanger

Heat Exchanger info

Island: **Tahiti**

Info Passed on by Adrian Diesel-Clinic owner Adrian Pataki Engineering Technician

+68987286083

svattila@gmail.com

There is no shop which specializes in Cupro-nickel heat-exchanger repair. To effect temporary repairs until your new heat-exchanger arrives, there are various radiator-shops in town, in the Titioro area, they are able to solder the damaged heat-exchanger using hard-solder, but i prefer to do it myself, so i don`t have an address or phone number. If the fault is not in the tube-stack, but in the cast-aluminium headertank, there is a welder in valley of Tipearui, right after the Karcher-shop, (Norbert +68987747093, speaks fluent French :))

Revision #1
Created 2 November 2024 06:04:36 by Frans
Updated 2 November 2024 06:05:19 by Frans