

Fiberglass, resins, gelcoat

Maintenance Marquises Service

Island: **Hiva Oa**

Maintenance Marquises Service Reported to do good fiberglass repair For more information, see Haulout

Blue Composites Tahiti

Island: **Tahiti**

📍 GPS decimal degrees: Lat -17.532973, Lon -149.581309 [GoogleMaps](#) [OpenStreetMap](#)

Blue Composites Tahiti Digue Ouest Motu Uta (15,137.43 km) 98713 Pape'ete 📍

ng@bluecompositestahiti.com

📞 [+68940576575](tel:+68940576575)



bluecompositestahiti.com/?fbclid=IwAR08SKBfsqmH0dgS9OsGWTraX02f5H7bNRlx1Inik5uQr030XzN6GSVmAU

5-2023 SV Tengah Consider reaching out to Nicholas at Blue Composites in Tahiti. His English is decent but his foreman, Alex, has near impeccable English. Consider using DeepL when writing him. I find in FP that you get much faster responses if you write in French. They are the best fiberglass shop in all of FP and he's a boatbuilder also. I presume they can get a stainless shop to help with the stainless internals.

Christian Fuller Fiberglass repair

Island: **Tahiti**

📞 [+68987790606](tel:+68987790606)

[✉ chfuller@mail.pf](mailto:chfuller@mail.pf)

Recommended by the 2016/2017 Super Yacht Guide. I just saw a spar he painted and it looked terrific (Jacaranda 2017) Christian speaks some English. Carpentry, Fiberglass & Spraying LP work

Fiberglass, Resins, Gelcoat

Island: **Tahiti**

Best stock in Tahiti Yacht Accessoire Marina Taina at Michel Balzer's or Sin Tung Hing but available at Ace, Nautisport, Siou Lee, Emile Vongue, Ocean 2000. See Marine Equipment

Luc Vacher Fiberglass work

Island: **Tahiti**

Luc Vacher Coponat [✆ +68987737919](tel:+68987737919)

Best to read the reports about him in the refrigerator section. May want to stay clear based on his shoddy business practices and work ethic. Repairs hulls, centerboards, rudders works with polyester and epoxy fiberglass, carbon, kevlar, foam, CP gel coat and paint.

2-2022 SV SV Luna I recently discovered a crack in one the stringers/lengthwise frame elements close to the keel I ended up hiring Luc Vaucher Coponat for the job. I am very happy about the whole process. Good work and good communication. I can definitely recommend him. For anyone interested.. The crack did not go into the stringer itself. It was the fiberglass bonding the stringer to the hull that had popped.

Ocean Sails Tahiti

Island: **Tahiti**

Michel [✆ +68987711686](tel:+68987711686)

[✉ oceansailstahiti@gmail.com](mailto:oceansailstahiti@gmail.com)

11-18 Michel made a fiberglass exhaust pot for SV Little Wing that fit the previous exhaust cylinder exactly. Joe highly recommends him

Peel Ply alternative

Island: **Tahiti**

Go to any fabric store and buy satin fabric, cheap and works exactly the same... Do not use plastic it will tear and you will tear your hair out picking it off... Have used satin fabric for 3 years in fiberglass workshop never any issues.

Poly Core (Vacuum Bagging)

Island: **Tahiti**

📍 GPS decimal degrees: Lat -17.527454, Lon -149.527402 [GoogleMaps](#) [OpenStreetMap](#)

Poly Core Composites 📞 [+68987347473](tel:+68987347473)

Contact: Manuarii 📧 contact@polycore.pf

🌐 www.facebook.com/Polycore.Composites.Tahiti/

Major builders of the racing Va'as

02-23 SV Hedonism used Polycore to do some required structural work and were very pleased. They came to the boat at Techni Marine to do the work

Sail The Way – Rudy

Island: **Tahiti**

Sail The Way – Rudy For more information, see Electronics (Marine)

Revision #1

Created 2 November 2024 01:03:18 by Frans

Updated 2 November 2024 04:13:04 by Frans